

PROSTAT Instruments & Applications

Utilization Matrix

Part Number	Description	Utilization Matrix												
		Grounds	Floors	Footwear	Work Surfaces	Equipment	People	Garments	Gloves & Cots	Raw Material	Production Aids	Packaging	Ionization	Process Analysis
PFM-711A(S)	Field Meter Set, Dual Rge		X	X		X	X			X	X	X	X	X
CPM-720	Charge Plate Monitor Assembly		X	X		X	X			X	X	X	X	X
CPM-760A	6 Charge Plate Monitor Assem.		X	X			X			X	X	X	X	
PCS-730	1kV Charging Source		X	X			X			X	X	X	X	X
PWS-610M	10ft Wrist Strap w/Snap Mod.		X	X		X	X			X	X	X	X	X
PHT-771	Psychrometer for Temp, Rh, Dew Point		X	X	X	X	X	X	X	X	X	X	X	X
PDT-740	Static Decay Timer		X							X	X	X	X	X
PGT-61-164	Advanced Int'l Ground Circuit Tester	X	X	X	X	X	X			X	X	X	X	X
GAP-005	Ground Adapter Plug	X	X	X	X	X	X			X	X	X	X	X
PRS-801-M	Wide Range Resistance System	X	X	X	X	X	X	X	X	X	X	X		X
PRS-801-W	NFPA 2.5" 5# Rubber Electrodes		X		X	X		X	X	X	X	X		X
PRS-800-L	10 Silicone Leads (CECC Ends)	X	X	X	X	X	X	X	X	X	X	X		X
PRS-800-INS	3x5 Insulated Test Bed		X		X					X	X			X
PRS-800-MTL	3x6 Stainless Steel Test Bed		X		X					X	X			X
PRS-800 CS	Cable Spacers 36 & 10 Inch, Set		X		X									
PGC-821	Garment Clip - 1 Pair							X						X
PSC-010	Pony Clamps 3" & 6"				X			X			X			X
PWA-805	Wrist Strap Auditor					X								
PRF-911	Concentric Ring Fixture								X	X	X	X		X
PTB-920	Dual Test Bed								X	X	X	X		X
PFP-861	Footplate with Snap Adapter		X	X		X	X			X	X	X		X
PGB-745 Kit	Decay Accessories Set Assembly									X	X	X		
PRF-912B	Micro Probe E12 Ohm C/Ring Pin Fixture					X				X	X	X		X
PRF-914B	Micro Probe E14 Ohm C/Ring Pin Fixture					X				X	X	X		X
PRF-922	Micro 2-Point Probe					X				X	X	X		X
PRF-922A-B	2-Point Adapter for PRF-912 & 914 Fixtures					X				X	X	X		X
PRV-913B	Min. Probe Verification 2-Side Fixture					X				X	X	X		X
PFC-721	Faraday Cup Assembly					X				X		X		X
PAN-750	Anemometer												X	X
PGA-710	AutoAnalysis System		X	X		X	X						X	X
CVM-780	Contact Voltmeter					X		X		X	X	X	X	X
PCF-825	PCF-825 Glove CAFÉ Fixture								X					X